



FU-CS



br- braun/braun/brun
 ge- gelb/yellow/jaune
 ws- weiß/white/blanc

0-10 V Extern	Potentiometer Extern	LTR/K 40 Temperatur Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	2 x LTR/K 40 Temperatur Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	LDF 500 Druckaufnehmer Art.Nr. 1322	LDF 500 + LTA 40 Druckaufnehmer + Temperatur (außen) Art.Nr. 1322 + Art.Nr. 1336	LGF 10 Luftgeschwindigkeit Art.Nr. 1325	2 x AFS 0-10V Absolute-Feuchte Art.Nr. 6532
Modus 1.01	Modus 1.01	Modus 2.01, 2.03	Modus 2.05	Modus 4.01	Modus 4.02	Modus 6.01	Modus 8.01


FU-CS



br- braun/braun/brun
ge- gelb/yellow/jaune
ws- weiß/white/blanc

0-10 V ext. des. value	Potentiometer ext. des. value	LTR/K 40 Temperature sensor Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	2 x LTR/K 40 Temperature sensor Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	LDF 500 Pressure sensor Art.Nr. 1322	LDF 500 + LTA 40 Pressure sensor + Temperature sensor Art.Nr. 1322 + Art.Nr. 1336	LGF 10 Air speed sensor Art.Nr. 1325	2 x AFS 0-10V Humidity sensor Art.Nr. 6532
Modus 1.01	Modus 1.01	Modus 2.01, 2.03	Modus 2.05	Modus 4.01	Modus 4.02	Modus 6.01	Modus 8.01

FU-CS



br- braun/braun/brun
ge- gelb/yellow/jaune
ws- weiß/white/blanc

0-10 V ext. selon le désir ajustment	Potentiometer ext. selon le désir ajustment	LTR/K 40 Sonde de température Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	2 x LTR/K 40 Sonde de température Art.Nr. 1323/24 (LTA 40 Art.Nr. 1336)	LDF 500 Sonde de pression Art.Nr. 1322	LDF 500 + LTA 40 Sonde de pression + Sonde de température Art.Nr. 1322 + Art.Nr. 1336	LGF 10 Sonde de vitesse d'air Art.Nr. 1325	2 x AFS 0-10V Sonde de humidité Art.Nr. 6532
Modus 1.01	Modus 1.01	Modus 2.01, 2.03	Modus 2.05	Modus 4.01	Modus 4.02	Modus 6.01	Modus 8.01